

### MarS a.s., Okružní II. čp. 239, 569 43 Jevíčko

SERVICE BULLETIN

#### CZECH REPUBLIC

 $\mathbf{C}$ 

#### SERVICE BULLETIN No. M ATL - 01 - 10

## ALTERNATIVE WAY OF USING RUBBER BANDS WITH ATL PARACHUTES

**1. CONCERNS:** Emergency parachutes:

ATL - 88, Type approval to use in civil aviation S-101-02/15-92,

ATL - 88/90, Type approval to use in civil aviation S-103-02/46-96,

ATL - 88/92 - S, Type approval to use in civil aviation S-102-02/44-96,

ATL - 88/98 - S, Type approval to use in civil aviation S- 82- 03,

ATL - 88 - 1, Authorization ETSO: EASA.210.1011 Rev. A,

ATL - 88/90 - 1, Authorization ETSO: EASA.210.1011 Rev. A,

ATL - 88/92 - S - 1, Authorization ETSO: EASA.210.1011 Rev. A,

ATL - 88/98 - S - 1, Authorization ETSO: EASA.210.1011 Rev. A.

**2. REASON:** Information for the users of ATL emergency parachutes.

3. PROCEEDING: During operation it is possible to replace currently used coupon rings and

rubber bands for rubber bands no. S7100 or S7110, measures 2" x 3/8", supplier PARA-GEAR EQUIPMENT CO. INC company or MarS a.s.

Company, business entry no. 406004000000.

**4. APPROVAL:** This Service Bulletin describes an alternative way of replacement of ruber

bands used with ATL parachutes as an unimportant change to technical conditions TPF 01 - 5248 - 89 of ATL emergency parachutes, which was

approved by a Design organization by MarS a.s. Jevíčko.

**5. VALIDITY:** From the issue date

6. ATTACHMENTS: -



# MarS a.s., Okružní II. čp. 239, 569 43 Jevíčko

SERVICE BULLETIN

### CZECH REPUBLIC

 $\mathbf{C}$ 

**7. ISSUE DATE:** In Jevíčko on June 15<sup>th</sup> 2010

Ing. Jaroslav Sedlák

Head of technical department, MarS a.s. Jevíčko

Stamp and signature:



